

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error
1	BRS	L1	203	((205/157 or 205/123 or 205/148 or 205/224 or 205/227 or 205/228 or 205/240 or 205/316 or 428/620 or 428/674 or 428/675 or 428/469 or 428/935 or 438/687 or 438/758).ccls.) and (electroplating or electroplated or electroplate)	USP AT; US- PGP UB; EPO ; JPO ; DER WEN T; IBM TD B	2004/04 /01 16:23			0
2	BRS	L2	20	((205/157 or 205/123 or 205/148 or 205/224 or 205/227 or 205/228 or 205/240 or 205/316 or 428/620 or 428/674 or 428/675 or 428/469 or 428/935 or 438/687 or 438/758).ccls.) and (electroplating or electroplated or electroplate) and (zinc or zn) and (copper or cu)	USP AT; US- PGP UB; EPO ; JPO ; DER WEN T; IBM TD B	2004/04 /01 16:23			0
3	BRS	L3	977 0	(205/157 or 205/123 or 205/148 or 205/224 or 205/227 or 205/228 or 205/240 or 205/316 or 428/620 or 428/674 or 428/675 or	USP AT; US- PGP UB; EPO ; JPO ; DER WEN	2004/04 /01 16:31			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	60	((205/157 or 205/123 or 205/148 or 205/224 or 205/227 or 205/228 or 205/240 or 205/316 or 428/620 or 428/674 or 428/675 or 428/469 or 428/935 or 438/687 or 438/758).ccls.) and (electroplating or electroplated or electroplate) and (zinc or zn) and (copper or cu) and oxygen) and (annealing or anneal or annealed) and oxygen	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/01 16:41	
2	IS&R	2	("6515368").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/01 16:56	

	Error Definition	Errors
1		0
2		0